Petersburg Airport

Pavement Condition Index - PCI
Measured Values for the Year 2002

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Kodiak Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2003

Airport Code: ADQ
Site No.: 50425.*A

PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Kodiak Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2004

Airport Code: ADQ
Site No.: 50425.*A

PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Kodiak Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2005

Airport Code: ADQ
Site No.: 50425.*A

PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60



Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Kodiak Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2006

Airport Code: ADQ
Site No.: 50425.*A



PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

N

Feet

0 500 1,000 1,500 2,000

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2003

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2004

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2005

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2006

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2007

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF

Petersburg Airport

Pavement Condition Index - PCI
Predicted Values for the Year 2008

Airport Code: PSG
Site No.: 50590.2*A

[ ] Branch - Section Identifier

Minimum PCI for Runways = 70
Minimum PCI for Taxiways and Aprons = 60





PCI Values	General Pavement Recommendations
85 - 100	Preventative Maintenance
70 - 84	Preventative / Corrective Maintenance
60 - 69	Corrective Maintenance / Overlay
55 - 59	Overlay / Rehabilitate
40 - 54	Rehabilitate
25 - 39	Reconstruct
10 - 24	Reconstruct
0 - 9	Reconstruct

Map complied 2002 (revised July 2003)
by Statewide Pavement Management, AK DOT&PF